




Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-33
(May, 1998)




**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-34
(May, 1998)**




**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-35
(May, 1998)**




**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-36
(May, 1998)**




**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-37
(May, 1998)**



**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-38
(May, 1998)**




**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-39
(May, 1998)**




APPENDIX E2

**GRAPHS OF VOLATILE ORGANIC COMPOUNDS OF POTENTIAL CONCERN
DETECTED IN SOIL VAPOR WELL NOS. 32 THROUGH 39, EVENT 7**


**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-32
(June, 1998)**



**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-33
(June, 1998)**



**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-34
(June, 1998)**



**Volatile Organic Compounds of Concern Detected in Soil Vapor Well B-35
(June, 1998)**

